










-  Duck Creek
-  Inland ponds / dams
-  Drainage lines
-  Constructed drainage channel
-  Lake Illawarra
-  Flood prone land (1 in 100 year flood event) \*
-  Ash dams
-  Asbestos repository
-  Contours (2m interval)

Source: *Corkery Consulting, 2010. Tallawarra Lands Landscape Assessment*  
 \* Flood information adapted from Bewsher Consulting

## Site Analysis - Geophysical + Hydrological

