

Plate 1: Asbestos Containing Roof Tiles KGO2



Plate 4: Telecommunications Tower – Library Rooftop



Plate 2: Lead Flashing Roof top KG02



Plate 5: Oil and Lubricant Storage in Maintenance Workshop



Plate 3: Diesel Oil Tank – Plant Room, Library Roof



Plate 6: Diesel storage in Hazardous Store (Maintenance)



Plate 7: Surface Staining and Corrosion Inside Hazardous Store



Plate 8: Chemical Storage in Woodworking Workshop



Plate 9: Chemistry Storeroom – chemical storage



Plate 10: Chemistry Storeroom November 2003



Plate 11: Photographic Studio and Washbay



Plate 12: Photography Dark Room Chemical Storage (developers, fixers)



Plate 13: Cleaning Chemicals Storage



Plate 14: Waste Storage Area and Loading Bay



Plate 15: Film Australia – UST located inside building, tank vent located outside of building



Plate 16 : Film Australia – Waste Storage Area and access road adjoining UTS northern property boundary



Plate 18: Film Australia – Chemical Waste Storage Area. Lack of Bunding, Inappropriate Labelling and Segregation



Plate 19: Film Australia - Waste Storage Area



Plate 17: Film Australia – Hazardous Chemical Storage



Plate 20: Film Australia – Waste Storage Area