




Existing condition of the site characterised by cleared land.



Typical built form in Penrose Subdivision fronting the site



Relationship between the site and existing residential area



Existing power easement that traverses the site

Figure 9 – Site Analysis