
APPENDIX C
Table C1 – Observations of Sandstone Outcrops
Drawing 6 – Location of Sandstone Outcrops

Photo A - Cut at eastern corner of Property 8 - north-eastern wall, facing north



Photo B - Cut at eastern corner of Property 8, south-east wall, facing south



Note: Deeply weathered defects

Photo C - Cut at north-eastern side of Property 8, facing north-east



Note: deeply weathered vertical joint

Photo D - Cut at south-eastern side of Property 8, facing south-east



Note: Open subvertical joints and bedding plans, possible instability

Photo E - Property 8 - Cut at south-eastern side of property, facing north-east



Photo A - Cut at north-eastern boundary of Property 9, adjacent to Constitution Road, facing north-east



Photo B - Cut at south-eastern boundary of Property 9, adjacent to Property 30, facing south-east




 Douglas Partners <i>Geotechnics • Environment • Groundwater</i>	CLIENT: Holdmark Constructions Pty Ltd			TITLE: Site Walkover Photographs Preliminary Geotechnical Assessment Proposed Shepherds Bay Urban Renewal	Project No: 71920
	DRAWN BY: SCP	SCALE: NTS	OFFICE: Sydney		Plate No: C2
	APPROVED BY: SCP		DATE: 19.07.2010		Revision: A

Photo A - Sandstone cliff at north-eastern side of Property 32, adjacent to Hamilton Crescent and Nancarrow Ave, facing north



Photo B - Sandstone cliff on Property 32, below Nancarrow Ave, facing north-west



Photo C - Sandstone cliff on property 32, below Nancarrow Ave, facing north-west



Photo D - Sandstone cliff, facing north, below Nancarrow Ave



Note: extremely low and very low strength sandstone, possible sheared zone


 Douglas Partners <i>Geotechnics • Environment • Groundwater</i>	CLIENT: Holdmark Constructions Pty Ltd			TITLE: Site Walkover Photographs Preliminary Geotechnical Assessment Proposed Shepherds Bay Urban Renewal	Project No: 71920
	DRAWN BY: SCP	SCALE: NTS	OFFICE: Sydney		Plate No: C3
	APPROVED BY: SCP		DATE: 19.07.2010		Revision: A

Photo A - sandstone cliff at north-eastern side of Property 32 below Hamilton Crescent, facing north




Photo B - sandstone cliff at north-eastern side of Property 32 below Hamilton Crescent, facing north-east



Photo C - cut in sandstone at north-eastern side of Property 32, facing east



Note: Thrust fault dipping south, fragmented, sheared rock above fault

 Douglas Partners <i>Geotechnics • Environment • Groundwater</i>	CLIENT: Holdmark Constructions Pty Ltd			TITLE: Site Walkover Photographs Preliminary Geotechnical Assessment Proposed Shepherds Bay Urban Renewal	Project No: 71920
	DRAWN BY: SCP	SCALE: NTS	OFFICE: Sydney		Plate No: C4
	APPROVED BY: SCP		DATE: 19.07.2010		Revision: A




 Douglas Partners <i>Geotechnics • Environment • Groundwater</i>	CLIENT: Holdmark Constructions Pty Ltd			TITLE: Site Walkover Photographs Preliminary Geotechnical Assessment Proposed Shepherds Bay Urban Renewal	Project No: 71920
	DRAWN BY: SCP	SCALE: NTS	OFFICE: Sydney		Plate No: C5
	APPROVED BY: SCP		DATE: 19.07.2010		Revision: A

Photo A - Sandstone outcrop below Property 40, adjacent to Belmore Road, facing north



Photo B - Sandstone outcrop at northern corner of intersection between Hamilton Crescent and Belmore Road



Photo B - Weathered, finely bedded sandstone below Property 40, adjacent to Belmore Road, facing north



Note: deeply weathered, possible Mittagong Formation


 Douglas Partners <i>Geotechnics • Environment • Groundwater</i>	CLIENT: Holdmark Constructions Pty Ltd			TITLE: Site Walkover Photographs Preliminary Geotechnical Assessment Proposed Shepherds Bay Urban Renewal	Project No: 71920
	DRAWN BY: SCP	SCALE: NTS	OFFICE: Sydney		Plate No: C6
	APPROVED BY: SCP		DATE: 19.07.2010		Revision: A

Photo A - Parsonage Street site, viewed from Loop Road, facing North



Photo B - Sandstone outcrop below Parsonage Street site, viewed from Loop Road, facing North



Note: Existing Ryde bridge at right

Photo C - Parsonage Street site, viewed from Anderson Park, facing east



Note: Sandstone outcrop in foreground, existing buildings at Parsonage Street site in background


 Douglas Partners <i>Geotechnics • Environment • Groundwater</i>	CLIENT: Holdmark Constructions Pty Ltd			TITLE: Site Walkover Photographs Preliminary Geotechnical Assessment Proposed Shepherds Bay Urban Renewal	Project No: 71920
	DRAWN BY: SCP	SCALE: NTS	OFFICE: Sydney		Plate No: C7
	APPROVED BY: SCP		DATE: 19.07.2010		Revision: A

Photo A - Cut into sandstone at nearby sites on Belmore Road, opposite Property 2



Photo B - Cut into sandstone at nearby sites on Belmore Road, opposite Property 2



Photo C - Sandstone flagging retaining wall on Property 9, adjacent to Property 10, facing east



Photo D - Sandstone boulder in filling in Nancarrow Avenue nature strip, outside Property 13




 Douglas Partners <i>Geotechnics • Environment • Groundwater</i>	CLIENT: Holdmark Constructions Pty Ltd			TITLE: Site Walkover Photographs Preliminary Geotechnical Assessment Proposed Shepherds Bay Urban Renewal	Project No: 71920
	DRAWN BY: SCP	SCALE: NTS	OFFICE: Sydney		Plate No: C8
	APPROVED BY: SCP		DATE: 19.07.2010		Revision: A

Photo A - Constitution Road Embankment (facing south-east), Property 1 at right



Photo B - Constitution Road Embankment (facing east)



Photo C - Constitution Road Embankment (facing east)



Photo D - Constitution Road Embankment (facing north-west), Property 9 at left




 Douglas Partners <i>Geotechnics • Environment • Groundwater</i>	CLIENT: Holdmark Constructions Pty Ltd			TITLE: Site Walkover Photographs Preliminary Geotechnical Assessment Proposed Shepherds Bay Urban Renewal	Project No: 71920
	DRAWN BY: SCP	SCALE: NTS	OFFICE: Sydney		Plate No: C9
	APPROVED BY: SCP		DATE: 19.07.2010		Revision: A

Photo A - Foreshore, viewed from near 146 Bowden Street, facing south-east



Photo B - Foreshore retaining wall, in front of property 32, facing south-east



Photo C - Foreshore batter - in front of property 34, facing south-east



Photo D - Batter toe - in front of property 34, facing ssouth-west



Note possible sandstone boulder at toe

Photo D - Foreshore batter - in front of property 34, facing north-west



Note existing stormwater drain at sandstone seawall



Douglas Partners
Geotechnics • Environment • Groundwater

CLIENT: Holdmark Constructions Pty Ltd

DRAWN BY: SCP

SCALE: NTS

OFFICE: Sydney

APPROVED BY: SCP

DATE: 19.07.2010

TITLE:

Site Walkover Photographs

Preliminary Geotechnical Assessment

Proposed Shepherds Bay Urban Renewal

Project No: 71920

Plate No: C10

Revision: A