

NOTES:

- 1: The ground surface level is estimated; however is largely unknown over the existing building footprint.
- 2: Subsurface profile is accurate at bore locations only and may vary significantly away from bores.
- 3: For details of Section B-B' refer Drawing 1

GEOLOGICAL PROFILE:

UNIT 1: Filling

UNIT 2: Residual clays and extremely weathered rock


UNIT 3: Laminite and fine to medium grained sandstone (Mittagong Formation)

UNIT 4: Medium to coarse grained sandstone (Hawkesbury Sandstone)

NOTE: Summary logs only. Should be read in conjunction with detailed logs.

	Core Loss		Concrete		Sandstone fine grained
	Silty Clay		Filling		Shaly Clay
	Asphaltic Concrete		Laminite		Silty clay
	Clay		Sandstone coarse grained		

ROCK STRENGTH	SOIL CONSISTENCY	TESTS / OTHER
EL - Extremely Low	vs - very soft	vl - very loose
VL - Very Low	s - soft	l - loose
L - Low	f - firm	md - medium dense
M - Medium	st - stiff	d - dense
H - High	vs - very stiff	vd - very dense
VH - Very High	h - hard	
		N - Standard penetration test value
		W - Water level
		BEL Bulk excavation level
		-? - Inferred boundary



CLIENT: Stamford Property Services Pty Ltd	
OFFICE: Sydney	DRAWN BY: GRB/LD
SCALE: 1:1000 (H) 1:100 (V) @ A3	DATE: 17.01.2011


TITLE: INTERPRETED GEOLOGICAL SECTION B - B'

Proposed Macquarie Village

110 - 114 Herring Road, Macquarie Park

PROJECT No:	72138
DRAWING No:	3
REVISION:	0

P:\72138 NORTH RYDE, Stamford Hotel GRB\Drawings\72138-4.dwg, 31/01/2011 9:31:30 AM



CLIENT: Stamford Property Services Pty Ltd

OFFICE: Sydney	DRAWN BY: GRB/LD
SCALE: 1:500 (H) 1:100 (V) @ A3	DATE: 17.01.2011


TITLE: **INTERPRETED GEOLOGICAL SECTION C - C'**

Proposed Macquarie Village

110 - 114 Herring Road, Macquarie Park

PROJECT No:	72138
DRAWING No:	4
REVISION:	0

P:\72138 NORTH RYDE, Stamford Hotel GRB\Drawings\72138-5.dwg, 31/01/2011 9:32:05 AM



P:\72138 NORTH RYDE, Stamford Hotel GRB\Drawings\72138-6.dwg, 31/01/2011 9:32:56 AM

