

APPENDIX B

PHOTOGRAPHS

Photo 1



Photo 2



Telecommunications Building - Interior

Photo 3



Telecommunications Building - Interior

Photo 4



Telecommunications Building - Interior

Photo 5



Telecommunications Building - Interior

Photo 6



Telecommunications Building - Interior

Photo 7



Telecommunications Building - Interior

Photo 8



Telecommunications Building - Interior

Photo 9



Telecommunications Building - Interior

Photo 11



Telecommunications Building - Exterior

Photo 10



Telecommunications Building - Interior

Photo 12



Telecommunications Building - Exterior

Photo 13




Telecommunications Building - Exterior

Photo 14



Telecommunications Building - Exterior

Photo 15



Telecommunications Building - Exterior

Photo 16



Telecommunication Building - Mezzanine

Photo 17



Telecommunications Building - Interior Mezzanine

Photo 18



Telecommunications Building - Interior Stair

Photo 19



Telecommunications Building - Interior

Photo 20



Telecommunications Building - Interior

Photo 21



Telecommunications Building - Interior

Photo 23



Clothing Store - Interior

Photo 22



Telecommunications Building - Interior

Photo 24



Clothing Store - Interior

Photo 25



Clothing Store - Interior

Photo 26



Clothing Store - Interior

Photo 27



Clothing Store - Interior

Photo 28



Clothing Store - Interior

Photo 29



Clothing Store - Interior

Photo 30



Clothing Store - Interior

Photo 31



Clothing Store - Interior

Photo 32



Clothing Store - Interior

Photo 33



Clothing Store - Interior

Photo 34



Clothing Store - Interior

Photo 35



Clothing Store - Interior

Photo 36



Clothing Store - Exterior

Photo 37



Clothing Store - Exterior

Photo 39



Clothing Store - Exterior

Photo 38



Clothing Store - Exterior

Photo 40



Scientific Services Building - Interior

Photo 41



Scientific Services Building - Interior

Photo 42



Scientific Services Building - Interior

Photo 43



Scientific Services Building - Interior

Photo 44



Scientific Services Building - Interior

Photo 45



Scientific Services Building - Interior

Photo 46



Scientific Services Building - Interior

Photo 47



Scientific Services Building - Interior

Photo 48



Scientific Services Building - Interior

Photo 49



Scientific Services Building - Interior

Photo 50



Scientific Services Building - Interior

Photo 51



Scientific Services Building - Interior

Photo 52



Scientific Services Building - Interior

Photo 53



Scientific Services Building - Interior

Photo 54



Scientific Services Building - Interior

Photo 55



Scientific Services Building - Interior

Photo 56



Scientific Services Building - Interior

Photo 57



Scientific Services Building - Interior

Photo 58



Photo 59



Scientific Services Building - Interior

Photo 60



Scientific Services Building - Exterior

Photo 61



Scientific Services Building - Exterior

Photo 63



Scientific Services Building - Exterior

Photo 62



Scientific Services Building - Exterior

Photo 64



Scientific Services Building - Exterior

Photo 65



Chief Mechanical Engineer's Building - Interior

Photo 66



Chief Mechanical Engineer's Building - Interior

Photo 67



Chief Mechanical Engineer's Building - Interior

Photo 68



Chief Mechanical Engineer's Building - Interior

Photo 69



Chief Mechanical Engineer's Building - Interior

Photo 71




Chief Mechanical Engineer's Building - Interior

Photo 70



Chief Mechanical Engineer's Building - Interior

Photo 72



Chief Mechanical Engineer's Building - Interior

Photo 73



Chief Mechanical Engineer's Building - Interior

Photo 74



Chief Mechanical Engineer's Building - Interior

Photo 75



Chief Mechanical Engineer's Building - Interior

Photo 76




Chief Mechanical Engineer's Building - Interior

Photo 77



Chief Mechanical Engineer's Building - Interior

Photo 78



Chief Mechanical Engineer's Building - Interior

Photo 79



Chief Mechanical Engineer's Building - Interior

Photo 80



Chief Mechanical Engineer's Building - Interior

Photo 81



Chief Mechanical Engineer's Building - Verandah

Photo 82



Photo 83



Chief Mechanical Engineer's Building - Verandah

Photo 84



Chief Mechanical Engineer's Building - Exterior

Photo 85



Chief Mechanical Engineer's Building - Exterior

Photo 86



Chief Mechanical Engineer's Building - Exterior

Photo 87



Chief Mechanical Engineer's Building - Exterior

Photo 88



Chief Mechanical Engineer's Building - Exterior

Photo 89



Chief Mechanical Engineer's Building - Exterior

Photo 91



Chief Mechanical Engineer's Building - Exterior

Photo 90



Chief Mechanical Engineer's Building - Exterior

Photo 92



Chief Mechanical Engineer's Building - Exterior

Photo 93



Chief Mechanical Engineer's Building - Exterior

Photo 95



Chief Mechanical Engineer's Building - Exterior

Photo 94



Chief Mechanical Engineer's Building - Exterior

Photo 96



Chief Mechanical Engineer's Building - Interior

Photo 97



Chief Mechanical Engineer's Building - Exterior

Photo 98




Chief Mechanical Engineer's Building - Exterior

Photo 99



Chief Mechanical Engineer's Building - Exterior

Photo 100



Chief Mechanical Engineer's Building - Exterior



Robert**Bird**Group

Sydney Office

Robert Bird Group Pty Ltd
ABN 67 010 580 248 ACN 010 580 248

Level 5
9 Castlereagh Street
Sydney NSW 2000
PO Box H38
Australia Square
Sydney NSW 1215
Australia

P: +61 (0) 2 8246 3200
F: +61 (0) 2 8246 3201

www.robertbird.com