
**Figure 1:** Vegetation on the slopes of the southern side of the lot.



**Figure 2:** View from the centre of the lot looking north (approx. 2m below the surrounding lots).



**Figure 3:** View of the ground surface at the centre of the lot (approx. 2m below the surrounding lots).



**Figure 4:** View from the centre of the lot looking north (approx. 2m below the surrounding lots).



**Figure 5:** View from the southern end of the lot looking west.



**Figure 6:** Southern end of the lot on George Evans Road.





Job No: 102166