

ENVILCOV00315AH Office Job No.: Valad Property Group 20.5.2008 Date started:

Borehole No.

Sheet

MW6

2 of 3

20.5.2008 Principal: Date completed:

NC Project: ESA 630-726 Princess Highway Tempe Logged by:

Во	Borehole Location: <b>Kennards Self Sto</b>							rage							
ı			ounti	ng:Truck m	ounted d	rill rig			ting:	slope:	-90°		R.L. Surface:		
_	e diame		rma	ition					thing:	bearin substance	g:		dati	um:	
method	2 penetration	support	water	notes samples, tests, etc	well details	RL	depth metres	aphic log	classification symbol	material soil type: plasticity or particle colour, secondary and mino	characteristics, r components.	moisture condition	consistency/ density index	structur additional ob	
ADT				E	$\boxtimes$	\$						М	S		
Air Blade /							- -			Sandy CLAY:Low plasticity, brow	n to red brown.	M	F	RESIDUAL.	
							7			Sandy Clay: Low plasticity, brown mottled grey.	to dark brown,	М	F		- -
				E			- 8 - 9 - 10			Gravelly SAND:Fine to medium to brown to brown. Gravel is medium weathered shale (mederate strender ironstone).	n grained, crushed	D	L		
AS AD	thod	au	ger d	crewing*	suppo C case		- - 1 <u>1</u> - - - 1 <u>2</u> N n	il	U <sub>50</sub> D	amples, tests undisturbed sample 50mm diameter disturbed sample	classification syn soil description based on unified c			S soft	y soft
RR W CT DT B V T TB	shown b	rol wa ca dia bla V I TO	ller/tri ashbo ble to atube ank bi bit bit bit bex ffix	cone ore ool	or wa	no rar ref	resistance aging to usal water lev shown	eel	D N N* Nc P Bs R E PID WS PZ ALT	aisturbed sample standard penetration test (SPT) SPT - sample recovered SPT with solid cone pressure meter bulk sample refusal environmental sample PID measurement water sample piezometer air lift test	based on unified c system  moisture D dry M moist W wet Wp plastic limit W_L liquid limit	iassificatio	оп	F firm St stiff VSt ver H har Fb frial VL ver L loos MD mee D der	y stiff d ole y loose se dium dense



ENVILCOV00315AH Office Job No.: Valad Property Group 20.5.2008 Date started:

Borehole No.

Sheet

MW6

3 of 3

20.5.2008 Principal: Date completed:

Project: ESA 630-726 Princess Highway Tempe NC Logged by:

		ehole Location: <b>Kennards Self S</b> model & mounting:Truck mounted drill rig							rage	•		Checked by: <b>BS</b>			
					nting:Truck	mounted (	drill riç	9		sting:	slope: -90°		R.L	. Surface:	
hole										thing:	bearing:		dat	um:	
method		Denetration 3	support		notes samples tests, et		RL	depth metres	aphic log	classification symbol	material soil type: plasticity or particle characteristics, colour, secondary and minor components.	moisture condition	consistency/ density index	structure and additional observations	
Air Blade								- 13 - 14 - 15 - 16 - - 17			Gravelly SAND: Fine to medium grained, pale brown to brown. Gravel is medium grained, crusher weathered shale (mederate strength, grey and ironstone). (continued)  Borehole terminated at 15m	D	L		
met AS AD RR W CT DT B V T TBX *bit e.g.	ζ sho		a w c d b V T T oy su	uge oller vash able iatul lank bit C bi ube	bit t	wate	tration 3 4 n rater 0/1/98 n date	o resistance anging to efusal B water leve e shown	e rel	notes, s U <sub>50</sub> D N N* Nc P Bs R E PID WS PZ ALT	amples, tests undisturbed sample 50mm diameter disturbed sample standard penetration test (SPT) SPT - sample recovered SPT with solid cone pressure meter bulk sample refusal environmental sample PID measurement water sample piezometer air lift test  classification: soil descriptio based on unifie system  moisture D dry M moist W wet Wp plastic lift W_L liquid lim	n d classificati		consistency/density index VS very soft S soft F firm St stiff VSt very stiff H hard Fb friable VL very loose L loose MD medium dense D dense VD very dense	



ENVILCOV00315AH Office Job No.: Valad Property Group 19.5.2008 Date started:

Borehole No.

Sheet

**MW7 / BH6** 

1 of 2

19.5.2008 Principal: Date completed:

NC Project: ESA 630-726 Princess Highway Tempe Logged by:

drill r	nodel	& m	ounti	ng:Truck m	ounted d	rill rig		Eas	ting: 2	229.7749 slope:	-90°		R.L	R.L. Surface: 13.73		
nole	diame	ter:						Nor	thing: 1	81.6385 bearing:			dat	um:		
	ling i		rma	ition						substance						
method	5 penetration	support	water	notes samples, tests, etc	well details	RL	depth metres	graphic log	classification symbol	material soil type: plasticity or particle cl colour, secondary and minor o	naracteristics, components.	moisture condition	consistency/ density index	structure and additional observations		
ADT				E			-			ASPHALT Gravelly SAND:Fine to medium gradark brown.Gravel is medium to coato medium sand, dark brown.	ained,brown to arse grained, fine	М	L	FILL.		
000000000000000000000000000000000000000				E		13	_ 1_ _	0 0		SAND: Medium to coarse grained, p		D	L	PID: 657ppm.  PID: 258ppm.		
				E		_12	- - - 2			\white and pink coloured intervals, (c Sandy CLAY:Low plasticity, dark b some medium gravels. Low oily odd	rown to black,	D	S	PID: 418ppm.		
				E		_11	-			Sandy CLAY: Medium plasticity, pa orange, yellow and grey. NO ODOL		M	F	RESIDUAL. PID: 233ppm.		
000000000000000000000000000000000000000							3 -			Gravelly SAND:Fine to medium gra brwon, gravel is medium grained, pa						
				E		_10	- <u>4</u> -							PID: 48ppm.		
	333333333333333333333333333333333333333			E		9	5 1 1			Slight oily odour.				PID: 1348ppm.		
041	lod			E	suppo	_8	- 6	0 0 0	notes -	amples, tests	classification sym	hole or	1	consistency/density index		
611 3 7 7	Ju	rol wa ca dia		re ool	penet 1 2 3	ration	N ni resistance reging to fusal	il :	U <sub>50</sub> D N N* Nc P Bs	undisturbed sample 50mm diameter disturbed sample standard penetration test (SPT) SPT - sample recovered SPT with solid cone pressure meter bulk sample	soil description based on unified cla system  moisture D dry M moist			VS very soft S soft F firm St stiff VSt very stiff H hard Fb friable		
3X	hown b	V I TO Tu	bit bit bex		<u>▼</u> 10		water leve shown flow	el	R E PID WS PZ	hulk sample				VL very loose L loose MD medium dense D dense		



Valad Property Group

Office Job No.: ENVILCOV00315AH

Date started: 19.5.2008

Borehole No.

Sheet

**MW7 / BH6** 

2 of 2

Principal: Date completed: 19.5.2008

Project: ESA 630-726 Princess Highway Tempe Logged by: NC

Bore	orehole Location: Kennards Self Sto									ora	rage				Checked by: <b>BS</b>			
drill r	mod	del	& n	noı	untii	ng:Truck m	ounted o	drill ri	g		Easting: 229.7749 slope: -90°					R.L	. Surface:	13.73
hole		_									Nor	thing: 1	181.6385 bearing:			datı	um:	
dri			inf	or	ma	tion				_	ma	terial	substance				ī	
method		s penetration	support		water	notes samples, tests, etc	well details	RL	dep	th es	graphic log	classification symbol	material soil type: plasticity or particle c	haracteristics, components.	moisture condition	consistency/ density index		ucture and al observations
ADT						E				7 8 9 9 9 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0			Gravelly SAND: Fine to medium gr brwon, gravel is medium grained, p (continued) Less penetration required.  Gravelly SAND: Fine to medioum gravel is medium to coarse, brown.  Groundwater observed.  Groundwater loss.  Shale: grey, moderate strength.  Borehole terminated at 9m	pale brown.	_ M	F	PID: 390ppm.	
meth AS AD RR W CT DT B V T TBX *bit s e.g.			a v d d b T T oy s	uge vas abl liatu lan bif C t	er di er/tric hboi e to ube ik bit t oit ex	ol	<del>-</del>	tratio 3 4 r r 0/1/98 n date	n no resista anging to efusal  water e showr	nil		notes, s U <sub>50</sub> D N N* NC P BS R E PIID WS PZ ALT	samples, tests undisturbed sample 50mm diameter disturbed sample standard penetration test (SPT) SPT - sample recovered SPT with solid cone pressure meter bulk sample refusal environmental sample PID measurement water sample piezometer air lift test	classification sy soil description based on unified system  moisture D dry M moist W wet Wp plastic limit W_L liquid limit	classificatio		consistency VS S F St VSt H Fb VL L MD D VD	vidensity index very soft soft firm stiff very stiff hard friable very loose loose medium dense dense very dense



ENVILCOV00315AH Office Job No.: Valad Property Group

Borehole No.

Sheet

MW9

1 of 2

30.5.2008 Date started: 30.5.2008 Principal: Date completed:

Project: ESA 630-726 Princess Highway Tempe NC Logged by:

Bore	orehole Location: <b>Kennards Self S</b>						Self .	Stoi					Checked by: <b>BS</b>			
				ng:Truck m				Easting: slope: -90°						. Surface:		
	diame			<u> </u>			•			thing:	bearing:		dati			
	lling		rma	ition							substance		-			
method	5 penetration	support	water	notes samples, tests, etc	we deta	ell ails	RL m	depth netres	graphic log	classification symbol	material soil type: plasticity or particle characteristics colour, secondary and minor components.	, moisture condition	consistency/ density index	structure and additional observations		
ADT				E	0 . 0 0	0 0		-	0 0		TURF / GRASS FILL: GRAVELLY SAND:fine to medium grained brown to dark brown. Gravel is fine to medium grained, pale brown to brown.	<u>d,</u> — M	L	PID: 0.7		
				E	0	o .		1			FILL: GRAVELLY SANDY CLAY low plasticity, brown to dark brown. Gravel is fine grained, pale brown to brown.	M	L	PID: 0.5		
				E	0 0	0 0		_ _ 2			SILTY CLAY: low to medium plasticity, brown to pale brown. Gravel is fine grained, pale brown to brown.  GRAVELLY SAND: fine to medium grained, grey pale brown. Gravel is fine grained, grey.	/ D	S L	RESIDUAL PID: 0.4		
All Diade				E				3						PID: 0.4		
,								- - - 4								
								- - - 5			becoming dark grey/ black shale.					
								-				M				
								<u>b</u> -								
								<u>7</u>								
neth AS AD RR V CT DT B	nod	ro wa ca di bla V	iger of ller/tri ashbo able to atube ank b bit	ore pol	C per	ter 10/	ation 4 no res rangin refusa	al ter leve	o o	U <sub>50</sub> D N N* Nc P Bs R	undisturbed sample 50mm diameter disturbed sample sample based on uni standard penetration test (SPT) SPT - sample recovered SPT with solid cone pressure meter bulk sample refusal environmental sample  undisture moisture D dry M moist vertusal W wet	ified classificati		consistency/density index VS very soft S soft F firm St stiff VSt very stiff H hard Fb friable VL very loose		
BX bit s	shown b	Tu by su	C bit ubex ffix DT			wat	date sho er inflow er outflo	v		PID WS PZ ALT	PID measurement Wp plastic water sample W <sub>L</sub> liquid I piezometer air lift test			L loose MD medium dense D dense VD very dense		



ENVILCOV00315AH Office Job No.: Valad Property Group

Borehole No.

Date started:

Sheet

MW9

30.5.2008

2 of 2

30.5.2008 Principal: Date completed:

Project: ESA 630-726 Princess Highway Tempe NC Logged by:

Bor	reho	chole Location: <b>Kennards Self S</b> model & mounting:Truck mounted drill rig						f Sto	rage	1		Checked by: <b>BS</b>			
drill	mod	el 8	mo	ounti	ng:Truck m	ounted dr	ill rig		Eas	sting:	slope: -90°		R.L	Surface:	
	diar									thing:	bearing:		dati	um:	
dr	_	_	1to	rma	ition				ma		substance				
method	u penetration		support	water	notes samples, tests, etc	well details	RL	depth metres	graphic log	classification symbol	material soil type: plasticity or particle characteristics, colour, secondary and minor components.	moisture condition	consistency/ density index	structure and additional observations	
Air Blade								- - 9 - 10 - 11 - 12 - 13 - - 14 - - - - - - - - - - - - - - - -			GRAVELLY SAND: fine to medium grained, grey to pale brown. Gravel is fine grained, grey. (continued, becoming light grey shale.  Borehole terminated at 11.6m	M	L		
AS AD RR W CT DT B V T	shod	n by	rol wa cal dia bla V I Tu	ger d ler/tri shbo ble to tube ink b bit bit bex	ool	suppoi C cas penetr 1 2 3 water water 10.	ration 4 no rar ref	water lev shown	el	notes, s U <sub>50</sub> D N N* NC P Bs R E E PIID WS PZ	amples, tests undisturbed sample 50mm diameter disturbed sample standard penetration test (SPT) SPT - sample recovered SPT with solid cone pressure meter bulk sample refusal environmental sample PID measurement water sample water sample piezometer  Classification s soil description based on unified system  moisture D dry M moist W wet Wp plastic lim VL liquid limi	i classificati		consistency/density index VS very soft S soft F firm St stiff VSt very stiff H hard Fb friable VL very loose L loose MD medium dense D dense	

# Appendix G PID Results

Contamination Assessment 630 - 726 Princes Highway, Tempe





#### form E5.1 - photoionisation detector results

client: Valad Properties Group office: LANE COVE

principal: date: 19/5/08 - 3/6/08

project: ESA, 630-276 Princes Hwy by: NC

location: Tempe, NSW checked by: BS

PID serial number: MINIRAE 2000 (SN: 110-900975) lamp voltage: 10.6eV

**PID Calibration Record** 

Date / Time of Calibration: 19/5/2008

Zero Calibration (0.0ppm) Actual Reading 0.00 ppm

Calibrated by: NC

Calibration gas: 100 ppm ISOBUTYLENE

Span Calibration (100 ppm) Actual Reading 99.8 ppm

SAMPLE ID	DEPTH	DURATION (mins)	BACKGROUND READING (ppm)	MAXIMUM READING (ppm)	LAST READING (ppm)	NOTES
BH6	0.5-0.7	1	0.00	657		19/5/2008
	1.0-1.2	1	0.00	258		
	1.5-1.7	1	0.00	418		
	2.5-2.7	1	0.00	233		
	3.5-3.7	1	0.00	118		
	4.5-4.7	1	0.00	348		
	5.5-5.7	1	0.00	200		
	7.0-7.2	1	0.00	390		
	8.5-8.7	1	0.00	318		
BH3	0.5-0.7	1	0.00	55	40.0	
	1.0-1.2	1	0.00	600	280	
	1.4-1.5	1	0.00	82	70	
	2.5-2.7	1	0.00	42.0	30.0	
	3.5-3.7	1	0.00	230	177	
	4.5-4.7	1	0.00	28.7	17.0	
	5.4-5.5	1	0.00	38.3	31.0	
BH9	1.0-1.2	1	0.00	400		

Fill in the test type as follows:-

BH ( ) = soil gas probe sample; (soil type - unified classification system in parentheses)

HS ( ) = headspace sample (with soil type-unified classification system in parentheses)

Doc. No. QP15/1-E5.1(DSD)





#### form E5.1 - photoionisation detector results

client:	Valad Properties Group	office:	LANE COVE
principal:		date:	19/5/08 – 3/6/08
project:	ESA, 630-276 Princes Hwy	by:	NC
location:	Tempe, NSW	checked by:	BS

PID serial number: MINIRAE 2000 (SN: 110-900975) lamp voltage: 10.6eV

**PID Calibration Record** 

Date / Time of Calibration: 19/5/2008

Zero Calibration (0.0ppm) Actual Reading 0.00 ppm

Calibrated by: NC

Calibration gas: 100 ppm ISOBUTYLENE

Span Calibration (100 ppm) Actual Reading 99.8 ppm

SAMPLE ID	DEPTH	DURATION (mins)	BACKGROUND READING (ppm)	MAXIMUM READING (ppm)	LAST READING (ppm)	NOTES
BH9	1.5-1.7	1	0.00	465		
	2.5-2.7	1	0.00	45.5		DUP 1
	3.5-3.7	1	0.00	242		
	4.2-4.4	1	0.00	328		
MW2	D1	1	0.00	235	193	
	D2	1	0.00	375	310	
	D3	1	0.00	685	600	
	D4	1	0.00	900	620	

HS ( ) = headspace sample (with soil type-unified classification system in parentheses)





#### form E5.1 - photoionisation detector results

client: Valad Properties Group office: LANE COVE

principal: date: 19/5/08 - 3/6/08

project: ESA, 630-276 Princes Hwy by: NC

location: Tempe, NSW checked by: BS

PID serial number: MINIRAE 2000 (SN: 110-009460) lamp voltage: 10.6eV

**PID Calibration Record** 

Date / Time of Calibration: 20/5/2008

Zero Calibration (0.0ppm) Actual Reading 0.00 ppm

Calibrated by: NC

Calibration gas: 100 ppm ISOBUTYLENE

Span Calibration (100 ppm) Actual Reading 99.9 ppm

SAMPLE ID	DEPTH	DURATION (mins)	BACKGROUND READING (ppm)	MAXIMUM READING (ppm)	LAST READING (ppm)	NOTES
MW6	0.5-0.7	1	0.00	1.8		20/5/2008 (New PID Unit)
	1.0-1.2	1	0.00	1.6		
	1.5-1.7	1	0.00	1.3		
	2.5-2.7	1	0.00	1.4		
	3.5-3.7	1	0.00	0.9		
	4.5-4.7	1	0.00	0.7		
	6.0-6.2	1	0.00	0.6		
	7.5-7.7	1	0.00	0.5		
	9.0-9.1	1	0.00	0.6		
BH4	0.5-0.7	1	0.00	0.3		
	1.0-1.2	1	0.00	0.5		
	1.5-1.7	1	0.00	0.8		
	2.5-2.7	1	0.00	0.8		
	3.5-3.7	1	0.00	0.7		
BH2	0.5-0.8	1	0.00	1.2		DUP 2, DUP 2A
	1.5-1.7	1	0.00	1.0		
	2.5-2.7	1	0.00	0.8		

Fill in the test type as follows:-

BH ( ) = soil gas probe sample; (soil type - unified classification system in parentheses)

HS ( ) = headspace sample (with soil type-unified classification system in parentheses)

Doc. No. QP15/1-E5.1(DSD)