

Project Title Project Address Project Suburb/Location

Wahroonga Estate: Phase 1 Contamination Assessment, Aerial Photograph 1970 148 Fox Valley Road Wahroonga NSW 2076

Project 45569.01


June 2008 Pate B 4



Wahroonga Estate: Phase 1 Contamination Assessment, Aerial Photograph 1982 148 Fox Valley Road Wahroonga NSW 2076

Project 45569.01

June 2008 Plate B 5




Douglas Partners

June 2008 Plate

B 6

Project 45569.01





June 2008 Plate B 7

APPENDIX C Site Photographs	



Photo 1: Fill



Photo 2: Fill

Phase 1 Contamination Assessment	Project	June	Plate
Wahroonga Estate	45569.01	2008	C 1
148 Fox Valley Road, Wahroonga NSW 2076			





Photo 3: Fill



Photo 4: Fill

Phase 1 Contamination Assessment	Project	June	Plate
Wahroonga Estate	45569.01	2008	C 2
148 Fox Valley Road, Wahroonga NSW 2076			





Photo 5: Fill, dumped waste material



Photo 6: Dumped empty 200 I heating oil tank

Phase 1 Contamination Assessment	Project	June	Plate
Wahroonga Estate	45569.01	2008	C 3
148 Fox Valley Road, Wahroonga NSW 2076			





Photo 7: Fill, dumped waste material



Photo 8: Fill, dumped waste material

Phase 1 Contamination Assessment	Project	June	Plate
roonga Estate	45569.01	2008	C 4
oad, Wahroonga NSW 2076			





Photo 9: Small package dangerous goods depot



Photo 10: Small package dangerous goods depot

Phase 1 Contamination Assessment	Project	June	Plate
Wahroonga Estate	45569.01	2008	C 5
148 Fox Valley Road, Wahroonga NSW 2076			





Photo 11: Underground fuel storage tank (UST) DG 15

Phase 1 Contamination Assessment	Project	June	Plate
Wahroonga Estate	45569.01	2008	C 6
148 Fox Valley Road, Wahroonga NSW 2076			

